

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: REDUCER ASSEMBLY

SYSTEM CREW ESCAPE SYSTEM

REVISION A

ASSY P/N: 8825071

SUBSYSTEM EMERGENCY OXYGEN SYSTEM

PAGE 22 OF 39

FMEA		NAME, QTY & DRAWING REF DESIGNATION	QTY	FAILURE MODE AND CAUSE	FAILURE EFFECT OR IMPACT	RATIONALE FOR ACCEPTANCE
REF	REV					
542		REDUCER ASSEMBLY, (2) 8825071	1/1	Mode: Reducer fails closed  Cause: • Piece part failure • Contamination	Loss of half or all available oxygen if second reducer fails	<ol style="list-style-type: none"> <li>1. Design Features               <ol style="list-style-type: none"> <li>a. The diaphragm spring is CRES 17-7PH, outer diameter .545 inches, wire diameter .100 inches, spring constant 424 lb/in ± 38 lb/in</li> <li>b. Filter is "microweave" wire mesh (104 CRES), 20 micron</li> <li>c. Diaphragm is 1.1 inch diameter, macron 150B41 impregnated with Dow Corning silicone rubber #DC35u, thickness = 0.26 ± 0.02</li> <li>d. Ball is made of 304 CRES</li> <li>e. Ball seat is batch controlled wespel SP-71</li> </ol> </li> <li>2. Test or Analysis to Detect Failure.               <ol style="list-style-type: none"> <li>a. <u>Acceptance Test</u> <ol style="list-style-type: none"> <li>(1) Proof load between ball terminals: 120 lb for 5 seconds in accordance with MIL C-5688</li> <li>(2) Functional test on cam actuation</li> <li>(3) Outlet flow and pressure test: 40-90 Lpm, 70 psi ± 5 psi</li> <li>(4) Functional test on seat prior to diaphragm assembly</li> <li>(5) Halogen purity test, flow oxygen to verify minimum purity of 95 percent</li> <li>(6) Functional test of reducer during oxygen charge/discharge cycle</li> </ol> </li> </ol> </li> </ol>

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: REDUCER ASSEMBLY

SYSTEM: CREW ESCAPE SYSTEM

REVISION: A

ASSY P/N: 0025071

SUBSYSTEM: EMERGENCY OXYGEN SYSTEM

PAGE 29 OF 39

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CNTY	FAILURE MODE AND CAUSE	FAILURE EFFECT OR INDICIA	RATIONALE FOR ACCEPTANCE
REF	REV					
542		REDUCER ASSEMBLY, (2) 0025071	1/1	Mode: Reducer fails closed  Cause: • Piece part failure • Contamination	Loss of half or all available oxygen if second reducer fails	(7) Seat leakage, body leakage test and cam actuation test (8) Relief valve cracking pressure test between 140 ± 10 psig at 3000 psig + 100 0 psig (9) Functional test at 38 slpm for 10 minutes minimum at 70 ± 10 psig. After 10 minutes, flow is increased to 90 slpm until gauge reads empty (10) The material is certified by the supplier by physical/chemical tests  <b>b. Certification:</b> (1) A similar reducer is qualified in accordance with Rockwell International procurement specification, emergency oxygen assembly, bailout instructor. (2) Proof pressure tested to 4500 psi + 10/-0 psig (3) Burst pressure tested to 7500 psi + 10/-0 psig for 1 minute (4) Endurance cycling: Inlet pressure varied from 3800 psig to 250 psig and returned to 3800 psig. This process is repeated for 250 cycles. (5) O <sub>2</sub> material compatibility test: Inlet pressure varied from 3750 psig to 250 psig and returned to 3750 psig. Process repeated 100 cycles. (6) 3750 psi leak test: No leakage is allowed (7) A similar system was live jumped at the Naval Weapons Center: 12 jumps from 25,000 feet, 4 jumps from 12,000 feet, 12 jumps from 10,000 feet, and 8 water drop jumps

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: REDUCER ASSEMBLY  
ASSY P/N: 8825071

SYSTEM: CREW ESCAPE SYSTEM  
SUBSYSTEM: EMERGENCY OXYGEN SYSTEM

DIVISION: A  
PAGE 24 OF 29

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CRTY	FAILURE MODE AND CAUSE	FAILURE EFFECT OR ITO ITEM	RATIONALE FOR ACCEPTANCE
REF	REV					
542		REDUCER ASSEMBLY, (2) 8825071	1/1	<p>Mode: Reducer fails closed</p> <p>Cause:  <ul style="list-style-type: none"> <li>• Piece part failure</li> <li>• Contamination</li> </ul> </p>	Loss of half or all available oxygen if second reducer fails	<p><u>Turnaround Testing</u> (in accordance with PIA 23025)</p> <ul style="list-style-type: none"> <li>a. Intermittent external leak check at 3000 psig ± 100 - 0 psig</li> <li>b. 24-hour leak/decay check at 3000 psig ± 100 - 0 psig</li> <li>c. Proof pressure test to 4500 psig ± 100 - 0 psig every 4 years</li> </ul> <p>3. Inspection:</p> <ul style="list-style-type: none"> <li>a. 100 percent DCAS inspection on all parts</li> <li>b. Cleaned and inspected for cleanliness to Level 100A in accordance with JSCM 5.122, Contamination Control Plan.</li> <li>c. Black light test - inspected for external contamination</li> <li>d. After reducer is assembled, the reducer is x-ray inspected to verify all parts and proper assembly</li> <li>e. Visual inspection to conformance of drawings.</li> <li>f. All moving parts are examined to ensure that they operate freely without sticking or binding</li> </ul>

# CRITICAL ITEMS LIST

ASSY NOMENCLATURE: REDUCER ASSEMBLY

SYSTEM: CREW/ESCAPE SYSTEM

REVISION: A

ASSY P/N: 8825071

SUBSYSTEM: EMERGENCY OXYGEN SYSTEM

PAGE 25 OF 39

FMEA		NAME, QTY & DRAWING REF DESIGNATION	CNTY	FAILURE MODE AND CAUSE	FAILURE EFFECT OR HAZARD	RATIONALE FOR ACCEPTANCE
REF	REV					
542		REDUCER ASSEMBLY, (2) 8825071	1/1	Mode: Reducer fails closed  Cause: • Piece part failure • Contamination	Loss of half or all available oxygen if second reducer fails	<p><u>Turnaround Inspection</u> (in accordance with PMA 23029)</p> <ol style="list-style-type: none"> <li>a. Visual inspection for damage</li> <li>b. Verify clean and inspected to cleanliness level 100A</li> </ol> <p>4. Failure History: None. A similar reducer is used in the B-1 bailout system and Dryden Flight Research Center.</p> <p>5. Operational Use:</p> <ol style="list-style-type: none"> <li>a. Operational effect of failure: Possible loss of crewmember</li> <li>b. Crew action: None.</li> <li>c. Crew Training: The crew is trained in the proper use of the emergency O<sub>2</sub> system.</li> <li>d. Mission constraints: None. Mission would be terminated prior to use of this equipment.</li> <li>e. In-flight checkout: None. Visual inspection of reducer/relief valve prior to use would not reveal failure.</li> </ol>

PREPARED BY: R. Allison B. Sauer

SUPERSEDING DATE: 10/24/88

APPROVED BY: J. D. Schlosser

DATE: 5/2/89